

## Firmware Release Note



The version (s) indicated here above has (have) been tested and validated by the Technical Support Department.

## **Technical Notes**

## Version 4.20

- Correction: [PLS300] Problem of frame capture size when switching capture source from RCS
- Correction: Automatic exit of menu "Motion correction" doesn't work when switching to a non-interlaced input
- Correction: Some status summary menu don't have the same duration
- Correction: [PLS300] The logo Chroma-key grabber position doesn't change on output 2
- Correction: When changing the HV size of a PIP, the H size suddenly goes to 0
- Correction: Strobbing effect for sources whose rate is really close to the output rate
- Correction: [PLS300] The tolerance setting of logo capture keying doesn't work
- Correction: [PLS300] When switching the logo capture source from RCS, the grabber doesn't disappear from the previous capture source

ANALOG WAY

Pioneer in Analog, Leader in Digital