ANALOG WAY®

Firmware Release Note

Products   EKS500 - EKS400

Date   18 March 2013

Version   4.20.26.00

**Remote Control Software Version (RS232)**   4.10.26.00

The version (s) indicated here above has (have) been tested and validated by the Technical Support Department.

Technical Notes

Version 4.20

- Feature: Add a shortcut to the configuration menu of the programmable effect keys
- Correction: Payload ID management for SDI outputs.

- Correction: Problem of frame capture size when switching capture source from RCS

- Correction: [EKS500] The keys effects shouldn't modify all the transition variables of a layer (ex : the "Cut" key shouldn't change the transition time and direction).

- Correction: Automatic exit of menu "Motion correction" doesn't work when switching to a non-interlaced input

- Correction: The logo Chroma-key grabber position doesn't change on output 2

- Correction: When changing the HV size of a PIP, the H size suddenly goes to 0

- Correction: Strobbing effect for sources whose rate is really close to the output rate

- Correction: The tolerance setting of logo capture keying doesn't work

- Correction: When switching the logo capture source from RCS, the grabber doesn't disappear from the previous capture source

- Correction: Presets layouts are not working in quadravision mode

MM:	**K = FF0C**
MF:	**K = 54F6**
CA:	**V = 0037**
FA:	**V = 0044**
TH:	**V = 0037**
CS:	V = 0009

Underlined = New Checksum

ANALOG WAY®
Pioneer in Analog, Leader in Digital