

Firmware Release Note



The version (s) indicated here above has (have) been tested and validated by the Technical Support Department.

Technical Notes

Version 4.20

- Correction: [OPS300] Payload ID management for SDI outputs.
- Correction: Problem of frame capture size when switching capture source from RCS.
- · Correction: Automatic exit of menu "Motion correction" doesn't work when switching to a non-interlaced input.
- Correction: The logo chroma-key grabber position doesn't change on output 2.
- Correction: When changing the HV size of a PIP, the H size suddenly goes to 0.
- Correction: Strobbing effect for sources whose rate is really close to the output rate
- Correction: [OPS300] Embed the payload ID of HDTV format in the SDI data output streams
- Correction: The tolerance setting of logo capture keying doesn't work
- Correction: When switching the logo capture source from RCS, the grabber doesn't disappear from the previous capture source

 $\begin{array}{cccc} \mbox{MM:} & \mbox{\underline{K} = $FF0C$} \\ \mbox{MF:} & \mbox{\underline{K} = $54F6$} \\ \mbox{CA:} & \mbox{\underline{V} = 0037} \\ \mbox{FA:} & \mbox{\underline{V} = 0044} \\ \mbox{TH:} & \mbox{\underline{V} = 0037} \\ \mbox{CS:} & \mbox{V = 0009} \\ \end{array}$

<u>Underlined = New Checksum</u>

